

Hong Kong Government Recognized Service Supplier Approved Laboratory of International Wool Secretariat

American National Standards Institute American Society for Testing and Materials

Hong Kong Association of Certification Laboratories Hong Kong Toys Council

British Standards Institute

TEST REPORT

NUMBER: TXT643669

DATE: JAN 23, 2002

MANUFACTURES LTD RM 3D 3/F LOYAL CTR

APPLICANT: TUNG KONG NON-WOVEN FABRIC

828 CHEUNG SHA WAN RD KLN

ATTN: MR FONG / MS LEUNG

SAMPLE DESCRIPTION:

TWO (2) PIECES OF SUBMITTED CUTTING SAID TO BE WOVEN FABRIC IN (A) RED QUILTED WITH 100 GM PADDING AND RED WOVEN LINING MARKED AS AND (B)

DATE RECEIVED/DATE TEST STARTED : JAN 22, 2002.

REF.: 100% POLYESTER NON-WOVEN FABRIC

(D.F.D)

CONCLUSION:

(A) (B)

APPEARANCE AFTER WASH

M

M = COMMERCIALLY ACCEPTABLE

F = FAIL

= NO COMMENT

TESTS CONDUCTED (AS REQUESTED BY THE APPLICANT)

APPEARANCE AFTER WASH (ISO 5077-1984/ISO 6330-1984, WASCATOR WASHING MACHINE-FRONT-LOADING HORIZONTAL ROTATING DRUM TYPE, TEST PROGRAMME 4A, 50C, 2KG LOAD IN 0.08% ECE REFERENCE DETERGENT AND 0.02% SODIUM PERBORATE SOLUTION, FOLLOWED BY LINE DRYING) :

SAMPLE (A)

AFTER ONE WASH

OBSERVATION :

- NO PADDING FIBRE WAS FOUND PENETRATING THROUGH THE RED WOVEN/QUILTED STITCHINGS.
- NO MATTING OR BUNCHING UP OF PADDING WAS FOUND.
- TINY CREASES WERE FOUND ON THE BODY OF THE WASHED SAMPLE.
- MODERATE PUCKERS WERE FOUND ALONG THE STITCHINGS OF THE WASHED SAMPLE.

THE GENERAL APPEARANCE OF THE WASHED SAMPLE WAS STILL ACCEPTABLE.

PREPARED AND CHECKED BY:

FOR INTERTEK TESTING SERVICES HK LTD

ERIC S.K. SIT

GENERAL MANAGER

TEXTILE AND FOOTWEAR DIVISION

KFCHAU / tewchak

Intertek Testing Services Hong Kong Ltd.

2/F., Garment Centre, 576 Castle Peak Road, Kowloon, Hong Kong. Tel: (852) 2173 8888 Fax: (852) 2786 1903

Hong Kong Government Recognized Service Supplier Approved Laboratory of International Wool Secretariat

Members of : American National Standards Institute American Society for Testing and Materials British Standards Institute

Hong Kong Association of Certification Laboratories Hong Kong Toys Council

TEST REPORT

NUMBER: TXT643669

TESTS CONDUCTED (AS REQUESTED BY THE APPLICANT)

2 APPEARANCE AFTER WASH (ISO 5077-1984/ISO 6330-1984, WASCATOR WASHING MACHINE-FRONT-LOADING HORIZONTAL ROTATING DRUM TYPE, SIMULATED HAND WASH PROGRAMME, MODIFIED TEMPERATURE AT 30C, 2 KG LOAD, IN 0.08% ECE REFERENCE DETERGENT AND 0.02% SODIUM PERBORATE SOLUTION, FOLLOWED BY LINE DRYING):

SAMPLE (B)

AFTER ONE WASH OBSERVATION:

- . NO PADDING FIBRE WAS FOUND PENETRATING THROUGH THE RED WOVEN/QUILTED STITCHINGS.
- . NO MATTING OR BUNCHING UP OF PADDING WAS FOUND.
- . TINY CREASES WERE FOUND ON THE BODY OF THE WASHED SAMPLE.
- . MODERATE PUCKERS WERE FOUND ALONG THE STITCHINGS OF THE WASHED SAMPLE.

THE GENERAL APPEARANCE OF THE WASHED SAMPLE WAS STILL ACCEPTABLE.