



Intertek Testing Services

Labtest

Hong Kong Government Recognized Service Supplier
Approved Laboratory of International Wool Secretariat

Members of:
American National Standards Institute
American Society for Testing and Materials
British Standards Institute

Hong Kong Association of Certification Laboratories
Hong Kong Toys Council

TEST REPORT

NUMBER: TXT648131

DATE: JAN 30, 2002

APPLICANT: TUNG KONG NON-WOVEN FABRIC
MANUFACTURES LTD
RM 3D 3/F LOYAL CTR
828 CHEUNG SHA WAN RD KLN
HK
ATTN: MR FONG / MS LEUNG

SAMPLE DESCRIPTION:

TWO (2) PIECES OF SUBMITTED CUTTING SAID TO BE 100% POLYESTER WOVEN
FABRIC IN BLACK QUILTED WITH 80GM PADDING AND BLACK WOVEN LINING
MARKED AS (A) T.K.A. AND (B) T.K.A.A..

DATE RECEIVED/DATE TEST STARTED : JAN 29, 2002.

REF. : T.K.A. (80GM)
T.K.A.A. (80GM)
NON-WOVEN FABRIC

CONCLUSION:

	(A)	(B)
APPEARANCE AFTER WASH	M	-
APPEARANCE AFTER COMMERCIAL DRYCLEANING	-	M

NOTE : M = COMMERCIALY ACCEPTABLE F = FAIL # = NO COMMENT

PREPARED AND CHECKED BY:
FOR INTERTEK TESTING SERVICES HK LTD

ERIC S.K. SIT
GENERAL MANAGER
TEXTILE AND FOOTWEAR DIVISION

ACHEUNG / tewchak

Intertek Testing Services Hong Kong Ltd.

2/F., Garment Centre, 576 Castle Peak Road, Kowloon, Hong Kong.
Tel: (852) 2173 8888 Fax: (852) 2786 1903

Attention is drawn to the terms and conditions printed overleaf.



Intertek Testing Services

Labtest

Hong Kong Government Recognized Service Supplier
Approved Laboratory of International Wool Secretariat

Members of:
American National Standards Institute
American Society for Testing and Materials
British Standards Institute

Hong Kong Association of Certification Laboratories
Hong Kong Toys Council

TEST REPORT

NUMBER: TXT648131

TESTS CONDUCTED (AS REQUESTED BY THE APPLICANT)

- 1 APPEARANCE AFTER WASH (ISO 5077-1984/ISO 6330-1984, WASCATOR WASHING MACHINE-FRONT-LOADING HORIZONTAL ROTATING DRUM TYPE, TEST PROGRAMME 4A, 50C, 2KG LOAD IN 0.08% ECE REFERENCE DETERGENT AND 0.02% SODIUM PERBORATE SOLUTION, FOLLOWED BY LINE DRYING) :

SAMPLE (A)

AFTER ONE WASH OBSERVATION :

- . NO PADDING FIBRE WAS FOUND PENETRATING THROUGHT THE WOVEN.
- . NO MATTING OR BUNCHING UP OF PADDING WAS FOUND.
- . TINY CREASES WERE FOUND ON THE WOVEN OF THE WASHED SAMPLE.
- . SLIGHT PUCKERS WERE FOUND ALONG THE STITCHINGS OF THE WASHED SAMPLE.
- . A FEW PADDING FIBRES WERE FOUND PENETRATING THROUGHT THE QUILTED STITCHINGS OF WOVEN.

THE GENERAL APPEARANCE OF THE WASHED SAMPLE WAS ACCEPTABLE.

- 2 APPEARANCE AFTER COMMERCIAL DRYCLEANING IN PERCHLOROETHYLENE :

SAMPLE (B)

AFTER ONE DRYCLEANING

OBSERVATION :

- . NO PADDING FIBRE WAS FOUND PENETRATING THROUGHT THE WOVEN QUILTED STITCHINGS OF WOVEN.
- . NO MATTING OR BUNCHING UP OF PADDING WAS FOUND.

THE GENERAL APPEARANCE OF THE DRYCLEANED SAMPLE WAS ACCEPTABLE.