

Hong Kong Government Recognized Service Supplier
Approved Laboratory of The Woolmark Company

Members of :
American National Standards Institute
American Society for Testing and Materials
British Standards Institute

Hong Kong Association of Certification Laboratories
Hong Kong Toys Council

NUMBER: TJ00419181

TEST REPORT

APPLICANT: TUNG KONG NON-WOVEN FABRIC
MANUFACTURES LTD
RM 3D 3/F LOYAL CTR
828 CHEUNG SHA WAN RD KLN
HK

DATE: SEP 05, 2003

ATTN: MR FONG/MR CHEUNG

SAMPLE DESCRIPTION :

TWO (2) PIECES OF SUBMITTED CUTTING SAID TO BE WOVEN FABRIC QUILTED WITH
PADDING IN LIGHT YELLOW MARKED AS (A) AND (B).

APPLICANT'S PROVIDED CARE INSTRUCTION :

HAND WASH 30°C

MACHINE WASH AND TUMBLE DRY

DATE RECEIVED/DATE TEST STARTED : SEP 01, 2003

ORDER NO. : -

STYLE NO. : -

BUYER'S NAME : -

MANUFACTURER'S NAME : -

REF. : TKDD

CONCLUSION:


	(A)	(B)
APPEARANCE AFTER WASH	M	-
APPEARANCE AFTER COMMERCIAL DRYCLEANING	-	M

NOTE : M = COMMERCIALY ACCEPTABLE
N/A = NOT APPLICABLE

F = FAIL # = NO COMMENT

REMARK : THE HAND WASHING TEMPERATURE AT 30C IS BELOW GENERAL PRACTICE.

PREPARED AND CHECKED BY:
FOR INTERTEK TESTING SERVICES HK LTD


ERIC S.K. SIT
GENERAL MANAGER
TEXTILE AND FOOTWEAR DIVISION

AC / hpyhuang

PAGE 1 OF 2

Intertek Testing Services Hong Kong Ltd.

2/F., Garment Centre, 576 Castle Peak Road, Kowloon, Hong Kong.
Tel: (852) 2173 8888 Fax: (852) 2786 1903 website: www.intertek-labtest.com

Attention is drawn to the terms and conditions printed overleaf.

TEST REPORT TESTS CONDUCTED (AS REQUESTED BY THE APPLICANT)

1 APPEARANCE AFTER WASH (ISO 6330-1984, WASCATOR WASHING MACHINE-FRONT-LOADING HORIZONTAL ROTATING DRUM TYPE, SIMULATED HAND WASH PROGRAMME, MODIFIED TEMPERATURE AT 30°C WITH 2 KG LOAD, IN 0.08% ECE REFERENCE DETERGENT AND 0.02% SODIUM PERBORATE SOLUTION, FOLLOWED BY LINE DRY):

(A)

AFTER ONE WASH

OBSERVATION :

- . NO PADDING FIBRE WAS FOUND PENETRATING THROUGH THE WOVEN AND THE STITCHINGS.
- . SLIGHT BUNCHING UP OF PADDING WAS FOUND.
- . TINY CREASES WERE FOUND ON THE WOVEN.
- . MODERATE PUCKERS WERE FOUND ALONG THE STITCHINGS OF WOVEN.

THE GENERAL APPEARANCE OF THE WASHED SAMPLE WAS STILL ACCEPTABLE.

2 APPEARANCE AFTER COMMERCIAL DRYCLEANING IN PERCHLOROETHYLENE:

(B)

AFTER ONE DRYCLEAN

OBSERVATION :

- . NO PADDING FIBRE WAS FOUND PENETRATING THROUGH THE WOVEN/QUILTED STITCHINGS.
- . SLIGHT BUNCHING UP OF PADDING WAS FOUND.

THE GENERAL APPEARANCE OF THE DRYCLEANED SAMPLE WAS ACCEPTABLE.