



Hong Kong Government Recognized Service Supplier
Approved Laboratory of The Woolmark Company

Members of :
American National Standards Institute
American Society for Testing and Materials
British Standards Institute

Hong Kong Association of Certification Laboratories
Hong Kong Toys Council

TEST REPORT

NUMBER: TJ00986344

APPLICANT: TUNG KONG NON-WOVEN FABRIC
MANUFACTURES LTD
RM 3D 3/F LOYAL CTR
828 CHEUNG SHA WAN RD KLN
HK

DATE: APR 22, 2005

ATTN: MS CHEUNG

SAMPLE DESCRIPTION :

THREE (3) PIECES OF SUBMITTED SAMPLE SAID TO BE WOVEN FABRIC QUILTED WITH
PADDING IN BLACK MARKED AS (A), (B) AND (C) CONTROL SAMPLE.

APPLICANT'S PROVIDED CARE INSTRUCTION :

HAND WASH 30C

MACHINE WASH AND TUMBLE DRY

DATE RECEIVED/DATE TEST STARTED : APR 18, 2005

ORDER NO. : -

STYLE NO. : -

BUYER'S NAME : -

MANUFACTURER'S NAME : -

REF. : L.F.

CONCLUSION:


	(A)	(B)
APPEARANCE AFTER WASH	M	-
APPEARANCE AFTER COMMERCIAL DRYCLEANING	-	M

NOTE : M = COMMERCIALLY ACCEPTABLE
N/A = NOT APPLICABLE

F = FAIL

= NO COMMENT

PREPARED AND CHECKED BY:
FOR INTERTEK TESTING SERVICES HK LTD


ERIC S.K. SIT
GENERAL MANAGER
TEXTILE AND FOOTWEAR DIVISION

MOK / mbswchow

Intertek Testing Services Hong Kong Ltd.

2/F., Garment Centre, 576 Castle Peak Road, Kowloon, Hong Kong.
Tel: (852) 2173 8888 Fax: (852) 2786 1903 website: www.intertek-labtest.com

TEST REPORT

NUMBER: TJ00986344

TESTS CONDUCTED (AS REQUESTED BY THE APPLICANT)

- 1 APPEARANCE AFTER WASH (ISO 6330-1984, WASCATOR WASHING MACHINE-FRONT-LOADING HORIZONTAL ROTATING DRUM TYPE, SIMULATED HAND WASH PROGRAMME, 40°C WITH 2 KG LOAD, IN 0.08% ECE REFERENCE DETERGENT AND 0.02% SODIUM PERBORATE SOLUTION, FOLLOWED BY LINE DRY):

(A)

AFTER ONE WASH

OBSERVATION :

- . NO PADDING FIBRE PENETRATING THROUGH WASHED SAMPLE.
- . NO MATTING OR BUNCHING UP OF PADDING WAS FOUND.
- . TINY CREASES ON WASHED SAMPLE.
- . SLIGHT FADING ON WASHED SAMPLE.
- . MODERATE PUCKERS ALONG QUILTED STITCHING.

GENERAL APPEARANCE : ACCEPTABLE

- 2 APPEARANCE AFTER COMMERCIAL DRYCLEANING IN PERCHLOROETHYLENE:

(B)

AFTER ONE DRYCLEAN

OBSERVATION :

- . NO PADDING FIBRE PENETRATING THROUGH WOVEN FABRIC.
- . NO MATTING OR BUNCHING UP OF PADDING WAS FOUND.
- . A FEW PADDING FIBRES PENETRATING THROUGH THE STITCHING.
- . SLIGHT FADING ON DRYCLEANED SAMPLE.

GENERAL APPEARANCE : ACCEPTABLE